




8350 Parkline Blvd
Suite 7
Orlando, FL 32809
(800) 612 6798



TESTIMONIAL Naples, FL Home



One Year Mold/Bacteria Resistance Test:

March of 2013 - The roof was cleaned, and the upper left-hand corner of the roof was coated with Nansulate® Crystal as a trial of its resistance to mold/bacteria growth in the tropical climate of Southwest Florida.

March of 2014 - This photo was taken a year later, and shows that while the mold/bacteria returned to the rest of the roof, the Nansulate® Crystal coated area remains clean and looking great.

Nansulate® Crystal insulating and mold resistant roof clear coat comes with a 10-year worry free warranty.

www.qes-usa.com

Photo is courtesy of Gulf Western Roofing.

- Nansulate
- Solar
- Wind
- Geothermal